Device update

Update using the web tool

SLZB-07/MGx:


- Go to https://smlight.tech/flasher/
- Press **Update SLZB-07 Firmware** button
- Select SLZB-07x/MGx dongle serial port
- Wait for connection
- Select firmware (Coordinator/Router/Thread)
- Flash firmware

If you get an error:

- Unplug your coordinator
- Open enclosure
- Connect pad **FLSH** with the **GND** or any metal part of the antenna (you can use tweezers or scissors)
- Plug the coordinator to your PC (**keep FLSH connected to the GND**)
- Run flashing

> TIP: You can insert a screwdriver near the antenna to make it easier to disassemble the case.





MG24
MG26
GND

SLZB-07pX:

- Go to https://smlight.tech/flasher/
- Press **Update SLZB-07pX Firmware** button
- Select SLZB-07pX dongle serial port
- Wait for connection
- Select firmware (Coordinator/Router/Thread)
- Flash firmware

If you get error:




- Refrash page
- Click on **Update SLZB-07pX Firmware** button again


Update using third-party tools

Flashing via Home Assistant addons

SLZB-07/MGx; https://github.com/home-assistant/addons/tree/master/silabs_flasher
Example config:



SLZB-07Px: https://github.com/tube0013/tubeszb_addons/tree/main/tzb-cc2652-flasher/
Example configuration:



Community firmware

SLZB-07/MGx

- https://github.com/darkxst/silabs-firmware-builder/tree/main/firmware_builds
- https://github.com/Nerivec/silabs-firmware-builder/releases

SLZB-07P7

- https://github.com/Koenkk/Z-Stack-firmware/releases

Please use **CC1352P7_coordinator_*** firmware for SLZB-07P7!
Incorrect firmware can brick your device!

SLZB-07P10

Sorry, there is no community firmware at this time.

Revision #5
Created 2025-09-29 13:10:48 UTC by Taras
Updated 2026-10-19 09:44:39 UTC by Taras